# SESLHD PROCEDURE COVER SHEET



NAME OF DOCUMENT	Radiation Safety - Quality Assurance in Radiotherapy
TYPE OF DOCUMENT	Procedure
DOCUMENT NUMBER	SESLHDPR/532
DATE OF PUBLICATION	November 2021
RISK RATING	Medium
LEVEL OF EVIDENCE	Legislative requirements  National Safety and Quality Health Service Standards:  Standard 1 – Clinical Governance
REVIEW DATE	March 2023
FORMER REFERENCE(S)	SESLHNPD/41 Quality Assurance Procedures for Radiation Therapy
EXECUTIVE SPONSOR or EXECUTIVE CLINICAL SPONSOR	Executive Director Operations
AUTHOR	Brent Rogers, Erin McKay
POSITION RESPONSIBLE FOR THE DOCUMENT	District Radiation Safety Officer rso.seslhd@health.nsw.gov.au
FUNCTIONAL GROUP(S)	Radiation Safety
KEY TERMS	Radiation safety; ionising radiation; x-rays; radiotherapy; quality assurance
SUMMARY	Quality assurance procedures for radiation therapy



Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

#### 1. POLICY STATEMENT

The South Eastern Sydney Local Health District (SESLHD) is committed, through a risk management approach, to protecting employees, contractors, students, volunteers, patients, members of the public and the environment from unnecessary exposure to radiation arising from systems and processes which use radiation apparatus and radioactive substances, whilst maintaining optimum diagnostic and therapeutic quality, therapeutic efficacy and patient care.

This document provides the procedures necessary to ensure compliance with this policy in relation to a quality assurance program in radiotherapy which places emphasis on equipment performance, patient safety and patient dose minimisation.

#### 2. BACKGROUND

A quality assurance program is necessary to provide sufficient confidence that requirements relating to safety and protection are satisfied. An effective Quality Assurance program will cover all aspects of radiation delivery including physical and technical aspects of equipment used, the clinical decision process, planning and administration of radiation.

#### 3. RESPONSIBILITIES

ARPANSA (2008a) describes the responsibilities of the medical professionals in a radiotherapy department. These responsibilities are adopted by SESLHD, including the "Radiation Medical Practitioner", "Radiation Therapist" and "Qualified Expert" (Radiation Oncology Medical Physicist).

#### 3.1 The Quality Assurance Committee

ARPANSA (2008a) recommends that a Quality Assurance Committee is formed in each department to help facilitate the development and monitoring of the quality assurance program. The Quality Assurance Committee should be comprised of representatives from all the relevant professional groups and have a focus on radiation safety, dosimetry, software testing, radiotherapy equipment maintenance and servicing and clinical processes associated with radiotherapy.

#### 3.2 Radiation Safety Officer

The radiation safety officer will oversee and provide advice on radiation safety within radiation therapy departments.

Revision 2 Trim No. T16/50571 Date: November 2021 Page 1 of 14



Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

#### 3.3 The Supplier

The supplier of radiotherapy equipment should incorporate current national standards in the design of their equipment or, when national standards are not defined, should ensure adherence to appropriate international standards. Accompanying documentation should make reference to which standards have been adopted. Implicit in this is the assurance that the required levels of radiation protection are met, all safety controls are in full working order and that there is redundancy within the system in case of failure of one component.

#### 3.4 The Equipment Servicing Agency

Equipment service personnel may be employed by the supplier of the equipment, by the organisation housing the equipment or by a third-party service company. The equipment service personnel will conform to the protection requirements and procedures of the organisation. The equipment servicing agency has a responsibility to employ appropriately trained and licensed personnel to service the equipment. The equipment servicing agency must work in close cooperation with the radiation oncology physicists to ensure that the physicists are aware at all times of the impact any service may have on the performance of the equipment.

#### 4. PROCEDURE

#### 4.1 Calibration, acceptance and tests of radiotherapy equipment

Australian or international standards applicable to radiotherapy include:

- Australian Standards (AS) 2900.10-2002. Quantities and units Nuclear reactions and ionizing radiations, 2002.
- AS/NZS 3200.2.1:1999. Medical electrical equipment Particular requirements for safety – Electron accelerators in the range of 1 MeV to 50 MeV identical to IEC 60601-2-1 – Ed. 2.0 – Medical electrical equipment – Part 2-1: Particular requirements for the safety of electron accelerators in the range 1 MeV to 50 MeV. 1998.
- AS/NZS 3200.2.11:1999. Medical electrical equipment Particular requirements for safety – Gamma beam therapy equipment Identical to IEC 60601-2-11 – Ed. 2.0 – Medical electrical equipment – Part 2: Particular requirements for the safety of gamma beam therapy equipment. 1997.
- AS/NZS 3200.2.17:1994. Approval and test specification Medical electrical equipment Particular requirements for safety Remote-controlled automatically-driven gamma-ray afterloading equipment identical to IEC 60601-2-17 Ed. 1.0 Medical electrical equipment. Part 2: Particular requirements for the safety of remote-controlled automatically-driven gammaray afterloading equipment. 1989.



## Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

- AS/NZS 3200.2.29:2000. Medical electrical equipment Particular requirements for safety – Radiotherapy simulators identical to IEC 60601-2-29 – Ed. 2.0 – Medical electrical equipment – Part 2-29: Particular requirements for the safety of radiotherapy simulators. 1999.
- AS/NZS 3200.2.9:1997. Approval and test specification Medical electrical equipment Particular requirements for safety Patient contact dosemeters used in radiotherapy with electrically connected detectors identical to IEC 60601-2-9 Ed. 2.0 Medical electrical equipment Part 2: Particular requirements for the safety of patient contact dosemeters used in radiotherapy with electrically connected radiation detectors. 1996.
- AS/NZS 3824:1998. Guidelines for radiotherapy treatment rooms design identical to IEC/ TR3 61859 – Ed. 1.0 – Guidelines for radiotherapy treatment rooms design. 1997.
- AS/NZS 4184.1:1994. Evaluation and routine testing in medical imaging departments – General aspects.
- AS/NZS 4184.3.1:2002. Evaluation and routine testing in medical imaging departments – Acceptance tests – Imaging performance of X-ray equipment for radiographic and radioscopic systems.
- AS/NZS 4213.1:1994. Radiotherapy simulators Functional performance characteristics identical to IEC 61168 – Ed. 1.0 – Radiotherapy simulators – Functional performance characteristics. 1993.
- AS/NZS 4213.2:1994. Radiotherapy simulators Guidelines for functional performance characteristics identical to IEC/TR2 61170 Ed. 1.0 Radiotherapy simulators Guidelines for functional performance characteristics. 1993.
- AS/NZS 4358:1996. Medical diagnostic X-ray equipment Radiation conditions for use in the determination of characteristics.
- AS/NZS 4434.1:1996. Medical electrical equipment Medical electron accelerators

   Functional performance characteristics identical to IEC 60976 Ed. 1.0 –
   Medical electrical equipment Medical electron accelerators Functional performance characteristics. 198.
- AS/NZS 4434.2:1996. Medical electrical equipment Medical electron accelerators

   Periodic function performance testing identical to IEC/TR 60977 Ed. 1.0 –
   Medical electrical equipment Medical electron accelerators in the range of 1 MeV to 50 MeV Guidelines for functional performance characteristics. 1989.



## Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

- AS/NZS 4495:1997. Radiotherapy equipment Coordinates, movements and scales. Identical to IEC 61217 - Consol. Ed. 1.1 (incl. am1) – Radiotherapy equipment – Coordinates, movements and scales. 2002.
- AS/NZS 4537:1999. Medical electrical equipment Dosimeters with ionization chambers as used in radiotherapy identical to IEC 60731 – Ed. 2.0 Medical electrical equipment – Dosimeters with ionization chambers as used in radiotherapy. 1997.
- AS/NZS 4580:1999. Medical electrical equipment Digital imaging and communications in medicine (DICOM) Radiotherapy objects identical to IEC/TR3 61852 Ed. 1.0 Medical electrical equipment Digital imaging and communications in medicine (DICOM) Radiotherapy objects. 1998.
- AS/NZS ISO 31000:2009. Risk management Principles and guidelines.
- AS/NZS ISO/IEC 27001:2006. Information Technology Security Techniques.
- International Electrotechnical Commission (IEC) 60601-2-8 Consol. Ed. 1.1 (incl. am1) Medical electrical equipment Part 2-8: Particular requirements for the safety of therapeutic X-ray equipment operating in the range 10 kV to 1 MV. 1999.
- IEC 62083 Ed. 1.0 Medical electrical equipment Requirements for the safety of radiotherapy treatment planning systems. 2000.
- IEC/TR 62266 Ed. 1.0 Medical electrical equipment Guidelines for implementation of DICOM in radiotherapy. 2002.

#### 4.1.1 Acceptance testing of radiotherapy equipment

The equipment or source test data must be compared to the technical specifications certified by the manufacturer or supplier. Full acceptance testing of new or modified radiotherapy treatment planning or dosimetry equipment should be completed by a certified radiation oncology medical physicist and is usually performed in cooperation with the installing engineers. The performance of the equipment must comply with Australian standards and/or international standards and in accordance with any requirements of the relevant regulatory authority.

Where non-standard equipment is used, the tests need to take due regard of protocols provided by the supplier and include a risk assessment.

The radiation oncology medical physicist should:

 ensure that shielding is adequate and safe prior to the commencement of any acceptance tests that involve production of radiation by the equipment being tested:

Revision 2 Trim No. T16/50571 Date: November 2021 Page 4 of 14



## Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

- ensure that records of all acceptance tests and commissioning data are kept and are readily available for later reference; and
- ensure that the equipment is clinically used only for modes of treatment for which it
  has been tested and accepted for use, and that all operators are duly informed of
  the limited conditions of use.

#### 4.1.2 Commissioning and calibration of radiotherapy equipment

Protocols for the dosimetric calibration of radiotherapy equipment should be in accordance with those adopted by the Australasian College of Physical Scientists and Engineers in Medicine (ACPSEM). Relevant national and international calibration protocols include the IAEA TRS-398 (2000), Klevenhagen et al (1996), Aukett et al (2005), Ma et al (2001) and IAEA TECDOC 1274 (2002).

All aspects of dosimetric calibration, including ensuring that all absolute dosimetry measurements are recorded, should be performed either by or under the supervision of a certified radiation oncology medical physicist. The physicist must confirm that the basic physics data stored in the planning computer system and the doses calculated by the computer treatment planning system are correct to within the accepted limits of accuracy.

All absolute dose calibrations and adjustments to these calibrations should be independently checked by another certified physicist, who may be in the same department. Once measurements have been completed, the records should be given to the person within the radiotherapy facility designated as having overall responsibility for physics data. Physical data procured during the acceptance testing and commissioning should be used as a reference baseline from which to monitor the performance of the radiotherapy equipment during subsequent quality control performance or operational tests.

All newly installed linear accelerators are also subject to an external audit prior to clinical release to ensure the radiation output is calibrated correctly. It is recommended that this process be carried out by the Australian Clinical Dosimetry Service (ACDS) as a Level 1b audit.

No radiotherapy treatment or planning equipment should be released for clinical use until a radiation oncology medical physicist is satisfied that the equipment is satisfactorily operating, calibrated and safe to use.

#### 4.1.3 Recommissioning

Radiotherapy equipment should be re-calibrated after initial commissioning and calibration, at least at the frequencies prescribed in the ACPSEM quality assurance recommendations (ACPSEM 1997) and also under the conditions prescribed in the current ACPSEM protocol. The recalibration procedure should be performed or overseen by a radiation oncology medical physicist who will ensure that the equipment will undergo sufficient recommissioning tests to confirm that the previous standards of operation are still satisfactory in accordance with the calibration recommendations for that equipment (ACPSEM 1997). The maximum interval between radiation output calibration (measured



### Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

under reference conditions and in accordance with the ACPSEM recommendations (ACPSEM 1997)) for all beam energies and types should not be greater than one year.

In addition to the initial acceptance and commissioning, the same test and measurement procedures should be followed whenever a major upgrade or overhaul of the equipment is undertaken. 'Major' would mean that the calibration or performance specification of the equipment might have changed sufficiently to warrant re-evaluation of the clinical suitability of the equipment or that the associated planning/treatment data needs to be updated. Some examples of changes considered major are as follows:

#### External beam radiotherapy

Critical situations to consider for X-ray tube equipment are the replacement of the X-ray tube itself, repairs or modifications to the high voltage and current controls and timer. Damage to filters or applicators may require detailed measurement as well as inspection after repair. Similarly, maintenance of the gun, target, waveguide, microwave source, dosimetry control circuits, ion chamber, flattening filter/scatterer replacement, machine tuning, light optics and mechanical bearing system, all require a reassessment of the equipment's calibration and accuracy of radiation delivery. A limited re-commissioning procedure is necessary when the X-ray tube or linear accelerator waveguide is replaced, affecting the dosimetry, or when major bearings are replaced, affecting the mechanical alignment of beam delivery.

#### Intra-operative radiotherapy

A linear accelerator for intra-operative radiotherapy in the treatment room, or a small mobile electron accelerator or low energy X-ray device in the operating theatre, should follow the same guidelines as described above.

#### Remote afterloading brachytherapy

Remote afterloading brachytherapy devices require a modified commissioning procedure after each new replacement radioactive source is loaded. For example, the accuracy of source activity, positional accuracy and source integrity should be determined prior to use. Any maintenance of the mechanical or electrical controls would necessitate a similar range of essential tests.

Revision 2 Trim No. T16/50571 Date: November 2021 Page 6 of 14



## Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

#### Manual brachytherapy - Seeds

Apart from regular quality assurance tests and safe practice housekeeping, individual radioactive sources should be tested if there is any indication of physical damage or wear, particularly if there is a possibility of radioactive source leakage from its inert, sealed container.

For brachytherapy, source strength may be measured by one of the techniques described in IAEA TECDOC 1274 (2002) or Nath et al (1997).

For sources that do not yet have a national standard, users should develop a constancy check calibrated against the vendor's standard and use this constancy check to verify the source strength. Other options also exist (for example the interpolative free-air standard method), but a clear protocol should be established before such sources are used clinically.

The measurement technique designed to check the source manufacturer details supplied with a source should take account of:

- any inaccuracy of measurements arising from the very high dose rate emitted from sealed radioactive sources; and
- the positional errors that may occur between the sealed radioactive source(s) and the radiation instrument used for the calibration.

#### Manual brachytherapy – Ru-106 Eye Plagues

A clear protocol should be established before such sources are used clinically.

#### 4.2 Repair and maintenance of the radiotherapy equipment

The preventative maintenance program should be carried out by the facility's or supplier's engineers, who are specifically trained in servicing the equipment. The radiation oncology medical physicist should be advised of the details of the work prior to the equipment returning to clinical use. There should be a clear sign or record book to show which staff group or individual is responsible for the equipment at any time. Following servicing, equipment should not be used clinically until released by the responsible physicist.

#### 4.3 Radiotherapy QA program

Each radiotherapy department in the LHD will have their own quality assurance program, the specific details of which will depend on the equipment complexity and quality assurance resources of the radiotherapy department. Refer to local department protocols for specific quality assurance procedures.

Each department must ensure that an up to date local procedure is documented and used for all quality assurance activities required on radiotherapy equipment.

Revision 2 Trim No. T16/50571 Date: November 2021 Page 7 of 14



## Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

All clinical procedures and workflow processes related to prescription, planning, checking and delivery of radiotherapy must be documented. This documentation should be reviewed frequently (at least once per year) and used for training new staff and as a reference point for design of quality assurance of all radiotherapy processes. Modifications to processes should be considered globally not in isolation from the whole treatment workflow. All disciplines should be involved in development and modification of radiotherapy processes relating to clinical process and workflow.

The following is an outline of the minimum quality assurance procedures recommended by ARPANSA (2008a).

#### 4.3.1 Linear accelerators

It must be ensured that:

- the equipment complies with the accepted tolerances listed in the ACPSEM QA recommendations (ACPSEM 1997) and the Australian Standard 4434:60601-1;
- the equipment is tested and calibrated at regular intervals in accordance with accepted recommendations for linear accelerators: ACPSEM (1997) and Klein et al (2009), noting that these documents are guidelines only and may be modified to suit the local requirements.

#### 4.3.2 Kilovoltage X-ray therapy units

The Quality Assurance program for kilovoltage units (up to 400 kVp or maximum 4.5 mm Cu HVL) must ensure that:

- the apparatus complies with accepted tolerances for kilovoltage X ray apparatus listed in the ACPSEM QA recommendations (ACPSEM 1997, Hill et al, 2018) for kilovoltage X-ray equipment; and
- the apparatus is tested and calibrated at regular intervals in accordance with the accepted protocol for kilovoltage X ray equipment frequencies listed in the ACPSEM QA recommendations (ACPSEM 1997, Hill et al, 2018)

#### 4.3.3 Brachytherapy Sources

The design and operation of the brachytherapy device must be considered to ensure satisfactory accuracy of treatment. Any computer program used in the dose calculation should be checked for accuracy after every modification or upgrade. Dempsey et al (2013) outlines the quality assurance recommendations for brachytherapy equipment to be adopted.

#### Source calibration

The sealed source activity or reference air kerma rate stated on the supplier's consignment details should be independently checked by an in-house radiation measurement.

Revision 2 Trim No. T16/50571 Date: November 2021 Page 8 of 14



## Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

Each high dose rate (HDR) source must be independently calibrated before any clinical use of the new source and the results of the check are to be documented. The new source strength should be incorporated into the brachytherapy treatment planning calculations (manual or computerised) for dose calculations unless the results of the check measurement vary by more than 5% from the certified activity or reference air kerma rate. In this case, the source should not be used until further independent verification of the source activity has been conducted. A brachytherapy source calibration device should comply with the tolerances listed in the ACPSEM QA recommendations (ACPSEM 1997, Dempsey et al 2013) for Brachytherapy Source Calibrators.

For low dose rate (LDR) sources, it is sufficient to test a subset (minimum 10%) of the sources.

#### Source sterilisation

Detailed consideration of the safety of methods of sterilisation is needed, to avoid damage to a sealed source that might result in leakage or rupture.

- Caesium-137 and Strontium-90 sources shall not be heat-sterilised. Heat-sterilisation requires purpose designed, temperature controlled equipment.
- Chemical sterilisation may be used, but attention should be paid to possible deleterious effects of some chemicals on sealed metal encapsulation of radioactive sources and on any attached threads.

Staff responsible for cleaning and sterilising of sealed sources shall be trained appropriately to prevent damage or loss, and follow the recommended shielding and sterilisation procedures. Sealed radioactive sources require adequate shielding during sterilisation and from then until immediately before their insertion in the patient. Shield design should provide protection for the body and head, including the eyes. Where possible, shielding of the fingers and hands from beta radiation should also be provided. Sources should be manipulated with long forceps, special remote handling devices or other suitable instruments. At times it may be impracticable to provide shielding protection for brachytherapy sources, and in such circumstances it becomes essential to maintain distance and minimise exposure time.

#### Brachytherapy contamination checks

Routine checks for integrity of the source, and for surface radioactive contamination of the source or associated equipment, should be performed with a minimum frequency of:

- high dose rate brachytherapy sources: each time before the source is replaced, or annually when in continuous use;
- plagues: prior to each application;

Contamination checks should be carried out by a person who is competent in operating the brachytherapy equipment or manipulating the source (as relevant) and in interpreting



## Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

the contamination test results. Where the results of the contamination testing of afterloading brachytherapy equipment remote control equipment indicate the presence of significant contamination from the source, persons using the equipment will need to:

- cease using it immediately;
- arrange for appropriate shielding to be applied to render the area safe for personnel, as appropriate;
- arrange for the appropriately trained and authorised personnel to review the equipment and identify and correct the problem and/or replace the source, as appropriate;
- arrange thorough decontamination of the equipment before resumption of use; and
- report the incident to the Radiation Safety Officer, the relevant regulatory authority and the vendor of the source.

If the results of the contamination testing of plaques indicate the presence of significant contamination, the affected plaque will need to be withdrawn from use. If the results of the contamination testing of applicators into which radioactive seeds have been loaded indicate the presence of significant contamination, the applicators will need to be thoroughly decontaminated before resumption of use.

Brachytherapy source containers often have small internal diameters so that it may not be possible to wipe test inside the source container, although a wipe test should be performed wherever possible. When a wipe test is not possible, tests should be made to detect radiation emitted by any radioactive contamination inside or on the outer surface of the source transfer system or applicator. Significant contamination of remote afterloading brachytherapy equipment is unlikely but is confirmed if the results of the contamination check indicate an activity of more than 200 Bq from the wipe test, or radiation greater than twice normal background from the check with a sensitive radiation detector.

Reporting to the relevant regulatory authority of significant contamination of remote afterloading brachytherapy equipment and sources is necessary so that relevant information can be disseminated to other sites using similar equipment.

#### Source Security

The recommendations in ARPANSA RPS11 (ARPANSA 2007) are to be followed with regard to brachytherapy source security. This includes the generation of a source security plan for any category 1, 2 or 3 radioactive sources. This plan must be approved by an EPA-accredited radiation security assessor.

#### Ultrasound QA

The recommendations in Pfeiffer et al (2008) are to be adopted for ultrasound systems used in prostate brachytherapy procedures.



## Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

#### 4.3.4 CT/Simulator

The physical data and accuracy of imaging modalities used for anatomical information and for quantitative purposes in treatment planning computer systems should be checked in accordance with the ACPSEM QA recommendations (ACPSEM 1997).

#### 4.3.5 Treatment planning systems

ACPSEM (1997) provides a guide of suggested quality assurance tests and frequencies for treatment planning systems and monitor unit calculations. IAEA TRS 430 (2004) provides more comprehensive and updated guidelines and should be used in conjunction with the ACPSEM recommendations. Independent treatment planning calculations and /or verification must be performed. The specific details of these checks will depend on the type of treatment and the equipment available. All such procedures should be documented locally and reviewed periodically to ensure their effectiveness and safety.

#### 4.3.6 Dosimetry equipment

Dosimetry equipment and other equipment used to perform QA on radiotherapy apparatus must itself be subject to quality assurance as specified in ACPSEM 1997. Records of all such QA must be kept securely and permanently as they form an integral component of the QA chain for the radiotherapy apparatus itself.

#### 4.3.7 Image registration software

Image registration software must be subject to quality assurance and control, following recommendations and guidelines outlined by Brock et al (2017).

#### 4.3.8 Record and Verify Systems

Quality assurance of record and verify systems used in radiotherapy must be subject to quality assurance and control, following recommendations and guidelines outlined by Shakeshaft et al (2014).

#### 4.3.9 Radiotherapy processes

International experience has demonstrated that radiotherapy errors or overdoses can occur due to breakdowns in clinical workflow processes as well as equipment failures or dosimetry calculation errors.

It is essential that the focus of quality assurance in radiotherapy departments is not restricted to just the calibration of the physical radiotherapy equipment used. The whole process from the time of the patient's first contact with the department until their final treatment follow-up, which may occur years after the treatment, needs to be considered in the context of radiation safety.

All clinical procedures and workflow processes should be assessed by a multidisciplinary team consisting of physicists, radiation therapists and radiation oncologists. This assessment should seek to identify any scope for introduction of treatment errors due to changes in work process or equipment or due to uncommon but potentially foreseeable circumstances.



## Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

The practice of keeping a log of incidents and near misses and evaluating these periodically is mandated by SESLHD risk and incident management policy directives. This log should include a record of occurrences that represent mistakes, errors or minor inaccuracies that were detected before they caused any harm. This will identify those categories of events which either have potential for serious harm or are less serious but frequently occurring. Periodic analysis of these records will enable the procedures in the department to be improved and reduce the possibility of significant errors in future.

#### 4.3.10 Dosimetry Audits

SESLHD is committed to ensuring the accuracy of the radiotherapy process is maintained. As such, a contract with the Australian Clinical Dosimetry Service (ACDS) is set up such that linear accelerator systems are audited annually. All newly installed linear accelerators are also audited prior to clinical release to ensure the radiation output is calibrated correctly.

#### 5. DOCUMENTATION

The following documentation must be maintained by the radiotherapy department manager:

- Records of acceptance and commissioning tests to be kept indefinitely either in paper or electronic form.
- Records of all periodic equipment QA to be kept indefinitely either in paper or electronic form.
- Records of Multidisciplinary QA meetings to be kept indefinitely either in paper or electronic form.
- Records of treatment planning system computer software validation following modifications and upgrades.

#### 6. AUDIT

The following audits are to be performed by the facility Radiation Safety Officer:

- Annual review of QA records.
- Annual review of minutes of QA Committee.

#### 7. REFERENCES

#### 7.1 SESLHD Resources

#### 7.2 NSW Ministry of Health Resources

- PD2017 032 Clinical Procedure Safety
- <u>PD2015\_043 Risk Management Enterprise-Wide Risk Management Policy and</u> Framework NSW Health

Revision 2 Trim No. T16/50571 Date: November 2021 Page 12 of 14



Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

#### 7.3 External Resources

- ARPANSA (2007), Code of Practice for Security of Radioactive Sources Radiation Protection Series (RPS) Publication No. 11, ARPANSA Yallambie 2007
- ARPANSA (2008), Code of Practice for Radiation Protection in the Medical Applications of Ionizing Radiation, ARPANSA, Yallambie 2008
- ARPANSA (2008a), Safety guide for Radiation Protection in Radiotherapy (RPS 14.3) ARPANSA, Yallambie 2008
- Aukett, R.J. et al Addendum to the IPEMB code of practice for the determination of absorbed dose for x-rays below 300 kV generating potential (0.035 mm Al-4 mm Cu HVL) Phys. Med. Biol. 50 pp 2739-2748, 2005
- Australasian College of Physical Scientists and Engineers in Medicine (ACPSEM), Recommendations for the Safe Use of External Beams and Sealed Brachytherapy Sources in Radiation Oncology, APESM 20(3), Supplement 1997
- Brock, K.K. et al, Use of image registration and fusion algorithms and techniques in radiotherapy: Report of the AAPM Radiation Therapy Committee Task Group No. 132. Medical Physics 44(7) 2017
- Dempsey, C. et al, ACPSEM brachytherapy working group recommendations for quality assurance in brachytherapy APESM 36: 387-396 (2013)
- Hill, R. et al, Australasian recommendations for quality assurance in kilovoltage radiation therapy from the Kilovoltage Dosimetry Working Group of the Australasian College of Physical Scientists and Engineers in Medicine APESM 41(4) pp 781-808 2018
- IAEA TECDOC 1274, Calibration of photon and beta ray sources used in brachytherapy IAEA, Vienna 2002
- IAEA TRS-398, Absorbed Dose Determination in External Beam Radiotherapy: An International Code of Practice for Dosimetry based on Standards of Absorbed Dose to Water IAEA, Vienna 2000
- IAEA TRS-430, Commissioning and Quality Assurance of Computerized Planning Systems for Radiation Treatment of Cancer IAEA, Vienna 2004
- Klein, E. et al, Task Group 142 report: Quality assurance of medical accelerators Med Phys 36(9), 2009
- Klevenhagen, S.C. et al, *The IPEMB code of practice for the determination of absorbed dose for x-rays below 300 kV generating potential (0.035 mm Al-4 mm Cu HVL; 10-300 kV generating potential)* Phys. Med. Biol, 41 pp 2605-2625, 1996.
- Ma, C.-M et al, AAPM protocol for 40-300 kV x-ray beam dosimetry in radiotherapy and radiobiology. Med Phys 28(6), 2001
- Nath et al, Code of practice for brachytherapy physics: Report of the AAPM Radiation Therapy Committee Task Group 56, Med Phys, 24(10), 1997

Revision 2 Trim No. T16/50571 Date: November 2021 Page 13 of 14

COMPLIANCE WITH THIS DOCUMENT IS MANDATORY



Radiation Safety: Quality Assurance in Radiotherapy

SESLHDPR/532

- Pfeiffer, D. et al, AAPM Task Group 128: Quality assurance tests for prostate brachytherapy ultrasound systems MedPhys 35(12), 2008
- Shakeshaft, J. et al, ACPSEM ROSG Oncology-PACS and OIS working group recommendations for quality assurance APESM 37(1), 2014

#### 8. REVISION AND APPROVAL HISTORY

Date	Revision No.	Author and Approval
August 2010	Draft	Area Radiation Safety Officer in conjunction with the Area Radiation Safety Committee
February 2011	0	Approved Combined Clinical Council
December 2015	1	Periodic Review
March 2020	2	Periodic Review – Anna Ralston, Simon Downes, Andrew Howie.
November 2021	2	Executive Sponsor updated to Executive Director Operations.  Approved by Executive Sponsor.